Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	6	(("6595068") or ("5967660") or ("4748854")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/17 14:55
L2	15	wafer near3 burn near3 test near3 mode near3 circuit	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/05/17 14:57
L3	10	(("5,980,103") or ("5,980,206") or ("6,761,073") or ("3,795,134") or ("4,933,239")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/17 15:02
L4	115	thermal near3 fatigue.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/05/17 15:06
L5	15	4 near4 (measur$5 test$4 detect$4 determin$4 sens$4 identi$6 evaluat$5 estimat$5 transducer gauge cell monitor$4 comput$5 inspect$5 meter calculat$4).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 15:07
L6	5628	thermal near3 fatigue	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/05/17 15:57
L7	358	6 near4 (measur$5 test$4 detect$4 determin$4 sens$4 identi$6 evaluat$5 estimat$5 transducer gauge cell monitor$4 comput$5 inspect$5 meter calculat$4)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 15:58
L8	0	7 and (rib appandage protur$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 15:52
L9	0	7 and (rib appandage protro$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 15:52
L10	2	7 and (rib appandage protro$5)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 15:59

L11	1	(test near3 (sample specimet piece) near3 (rib appandage protro$5)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 15:55
L12	608	((sample specimet piece) near3 (rib appandage protro$5)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 15:55
L13	723	12 thermal near3 fatigue.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/05/17 15:55
L14	0	12 and thermal near3 fatigue.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/05/17 15:56
L15	2	12 and thermal near3 fatigue	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/05/17 15:56
L16	115	thermal near3 fatigue.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/05/17 15:57
L17	15	16 near4 (measur$5 test$4 detect$4 determin$4 sens$4 identi$6 evaluat$5 estimat$5 transducer gauge cell monitor$4 comput$5 inspect$5 meter calculat$4)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 15:58
L18	49	6 near4 (measur$5 test$4 detect$4 determin$4 sens$4 identi$6 evaluat$5 estimat$5 transducer gauge cell monitor$4 comput$5 inspect$5 meter calculat$4).ti.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 15:58
L19	28	7 and (rib appendage protro$5 protru$5)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/05/17 16:00